


Prototype detector testing in liquid argon (underground summer)




Marik Barnabe Heider
Konstantin Gusev
Oleg Chkvorets
Stefan Shoenert

Goals of summer measurements


- Investigation of prototype inside LAr:
 -
 - Quality of contacts
 - Leakage current
 - Refill operations of the dewar
 - Long-term measurements





GERDA meeting, Milano, Nov 14, 2006




Konstantin Gusev, RRC 'KI' and JINR
















Problems (in order of appearance)


1. Breakdown in argon gas (not liquid!!!)
after 2000 V






Problems (in order of appearance)

1. Breakdown in argon gas after 2000 V
2. Bending of support



Torque, N×cm	R_{RT} , Ω
40	49.8
50	42.7
55	38.3
60	37, but bending





Problems (in order of appearance)

1. Breakdown in argon gas after 2000 V
2. Bending of support
3. Increase of leakage current after 25th cycle

Refurbishment of detector

(new implantation and passivation)





Problems (in order of appearance)

1. Breakdown in argon gas after 2000 V
2. Bending of support
3. Increase of leakage current after 25th cycle
4. Increase of forward resistivity

Normal signal contact before refurbishment:

- At room temperature: $R_{RT} \sim 60 \Omega$
- At liquid argon temperature: $R_{LAr} \sim 2 \text{ k}\Omega$

After refurbishment with soldered signal contact:

■ First immersion

- $R_{RT} = 39 \Omega$ $R_{LAr} = 2.7 \text{ k}\Omega$
- $U = 4000 \text{ V} \rightarrow I = 800 \text{ pA} \rightarrow \text{FWHM} = 3.7 \text{ keV}$

■ Second immersion


- $R_{RT} = 35 \Omega$ $R_{LAr} = 10 \text{ k}\Omega$
- $U = 4000 \text{ V} \rightarrow I = 800 \text{ pA} \rightarrow \text{FWHM} = 5.5 \text{ keV}$

■ Third immersion

- HV contact on bottom
- $R_{RT} = 38 \Omega$ $R_{LAr} = 8.5 \text{ k}\Omega$
- $U = 4000 \text{ V} \rightarrow I = 800 \text{ pA} \rightarrow \text{FWHM} \sim 4.5 \text{ keV}$


Start of long-term test

Leakage current history of prototype



Leakage current of prototype

Leakage current measured once per minute



Preliminary conclusion

- Breakdown in argon gas – solved
- No other specific argon problems
- Bending of support – solved
- Leakage current was stable during 2 months
- IR shield needed
- Boiling protection needed